



COMMAND CONSOLE VENTS

OVERVIEW

In order to reduce the build-up of excessive heat inside the lower command console on the Sutphen custom chassis, five (5) vents will be added. There will be three (3) vents in the lift-up lid and one (1) each side on the triangular portions. You will begin to see these on production units going forward.

