SUTPHEN CORPORATION SALES TECHNICAL BULLETIN



WARD DIESEL NoSMOKE FILTERS

OVERVIEW

For many years, the Ward Diesel Filter Systems NoSmoke & NoSmoke2 filters have been widely used on fire apparatus to filter out exhaust fumes and soot in lieu of a station mounted exhaust extraction system (Plymovent, Nederman, etc.). With the increased emissions regulations starting in 2007, we have seen a decrease in requests for these systems. However, we have begun to see an increase in popularity over the past year or so.

For those that may not be familiar with the Ward systems, here is a link to their website: http://www.warddiesel.com/post.php?pid=23

The filter (black assembly shown below) installs just before the exhaust tip:



With the complexity of the 2007+ exhaust after-treatment systems and the requirement for each system to be approved by Cummins, there has been a lot of recent discussion and concern if the Ward Diesel filter systems are acceptable to use and if they affect any of the Cummins warranties.

Created: 5/25/2017

By: C. Green

Revised: --

SUTPHEN CORPORATION SALES TECHNICAL BULLETIN



WARD DIESEL NoSMOKE FILTERS

OVERVIEW

Some of our early correspondence with Cummins led us to believe that the installation of a Ward Diesel filter system would automatically void the engine warranty on 2007+ engines. Recent discussions and correspondence with Cummins have corrected that misconception.

Below is the stance that Cummins has provided regarding the use of any Ward Diesel NoSmoke/NoSmoke2 systems. This is the same stance that Sutphen and our representatives will also take.



Service Bulletin

Cummins Inc. Warranty Position on the Use of Products Not Manufactured or Sold by Cummins Inc.

Cummins Inc. engine warranty covers engine failures that result from defects in Cummins Inc. material or factory workmanship, under normal use and service. Cummins Inc. engine warranty does **not** cover engine failures resulting from the use of products **not** manufactured or sold by Cummins Inc.

Cummins Inc. neither approves nor disapproves the use of products not manufactured or sold by Cummins Inc.

Ward Diesel has provided some of our customers with a Product Liability Insurance document (included on next page) to "cover any damage to a vehicle that is caused specifically by the Standard NO SMOKE Filter System or NO SMOKE 2 Filter Systems providing the system is installed by Ward Diesel Factory Direct Service Technicians."

If you have any additional questions or concerns, please contact your Sales Territory Manager.

SUTPHEN CORPORATION SALES TECHNICAL BULLETIN



WARD DIESEL NoSMOKE FILTERS

1580 Lake Street Elmira, NY 14901 Phone: 800-845-4665

Fax: 607-739-7092

WARD DIESEL FILTER SYSTEMS

www.warddiesel.com

Memo: Ward Diesel Filter System's Product Liability Insurance

NO SMOKE and NO SMOKE 2 Filter Systems

Date: June 25, 2015

This memo is in reference to both the Standard NO SMOKE Filter System and the NO SMOKE 2 Filter System as it relates to installations on Fire and EMS Vehicles.

Ward Diesel Filter Systems is covered by Product Liability Insurance that would cover any damage to a vehicle that is caused specifically by the Standard NO SMOKE Filter System or NO SMOKE 2 Filter Systems providing the system is installed by Ward Diesel Factory Direct Service Technicians.

The Standard NO SMOKE Filter System Started being installed in the early 1980's and the NO SMOKE 2 Filter System started being installed around August of 2007. To date there have been no claims of any product damage caused by either the Standard NO SMOKE or NO SMOKE 2 Filter Systems.

Ward Diesel Factory Direct Service Technicians follow all the procedures and guidelines provided by the engine manufacturers to make certain that there are no issues with any Manufacturer Warranties.

If there are any further questions please contact Ward Diesel Filter Systems at 1-800-845-4665.

